

Know Your Jack

PUMP PLUNGER

OIL FILLER PLUG

RESERVOIR

RESERVOIR

RAM

OIL LEVEL: It is recommended that the oil level is kept at approximately 12mm below the filler hole level of the power unit.

